



GE Medical Systems

Technical Publications

Direction 2166910–100

Revision 16

AMX–4+ Documentation (Model 2169360, 2236420 & 2275938 Series)

Copyright© 1996, 1997, 1998, 1999, 2000, 2001 By General Electric Co.

TABLE OF CONTENTS

TAB	NUMBER	TITLE
1	2173221-100	AMX-4+ RATINGS AND SPECIFICATIONS (MODEL 2169360, 2236420 & 2275938 SERIES)
2	2173222-100	AMX-4+ INSTALLATION (MODEL 2169360, 2236420 & 2275938 SERIES)
3	2173223-100	AMX-4+ CALIBRATION (MODEL 2169360, 2236420 & 2275938 SERIES)
4	46-013288	BLEEDER, HIGH-VOLTAGE DUAL TYPE T8005G AND C1515A CONNECTION... APPLICATIONS
5	2173224-100	AMX-4+ FUNCTIONAL CHECKS (MODEL 2169360, 2236420 & 2275938 SERIES)
6	2173225-100	AMX-4+ SERVICE (MODEL 2169360, 2236420 & 2275938 SERIES)
7	2196272-100	HIGH VOLTAGE CABLE INSTALLATION AND TROUBLESHOOTING PROCEDURES
8	2173227-100	AMX-4+ PERIODIC MAINTENANCE (MODEL 2169360, 2236420 & 2275938 SERIES)
9	2190775-100	STRANDED STEEL CABLE INSPECTION
10	2173228-100	AMX-4+ RENEWAL PARTS (MODEL 2169360 SERIES)
	2237257-100	AMX-4+ RENEWAL PARTS (MODEL 2236420 & 2275938 SERIES)
11	2173229-100	AMX-4+ SCHEMATICS (MODEL 2169360, 2236420 & 2275938 SERIES)

THIS PAGE INTENTIONALLY LEFT BLANK.

REVISION HISTORY

REV	DATE	REASON FOR CHANGE
A	October, 1996	Initial documentation.
0	Dec. 13, 1996	Initial release.
1	Mar. 7, 1997	Changes to 2173221-100, 2173222-100, 2173224-100, 2173225-100, 2173227-100, 2173228-100, 2173229-100. Deleted 46-017538.
2	Mar. 28, 1997	Change to 2173228-100.
3	June 24, 1997	Changes to 2173225-100, 2173277-100, 2173228-100, 2173229-100.
4	Aug. 14, 1997	High Impact Inspection: Changes to 2173221-100, 2173222-100, 2173223-100, 2173224-100, 2173225-100, 2173227-100, 2173228-100, 2173229-100. Added 46-013288, 2190775-100 and 2196272-100.
5	Sept 16, 1997	Added reference to Keithly Noninvasive divider to 2173221-100 and 2173223-100. Updated 2173221-100 and 2173223-100.
6	Dec. 1, 1997	Changes to 2173228-100.
7	Dec. 10, 1997	Changes to 2173222-100 and 2173228-100.
8	Sept. 23, 1998	Changes to 2173228-100.
9	Dec. 7, 1998	Updated 2173228-100.
10	Apr. 12, 1999	Added 2237257-100. Revised 2173221-100, 2173222-100, 2173223-100, 2173224-100, 2173225-100, 2173227-100, 2173229-100, 4-013288.
11	May 6, 1999	Revised 2173224-100 and 2237257-100.
12	July 14, 1999	Revised 2173224-100.
13	Mar. 7, 2000	Revised 2173228-100.
14	Aug. 8, 2000	Revised 2173228-100 and 2237257-100.
15	Nov. 8, 2000	Added 2275938 Series to 2173221-100, 2173222-100, 2173223-100, 2173224-100, 2173225-100, 2173227-100, 2237257-100, and 2173229-100. Corrected part # of spanner wrench to 46-404295G1 in 2196272-100.
16	Dec. 13, 2001	Revised 2173228-100 and 2237257-100.

LIST OF EFFECTIVE PAGES

PAGE NUMBER	REVISION NUMBER	PAGE NUMBER	REVISION NUMBER	PAGE NUMBER	REVISION NUMBER
Title Page	16	Direction 46-013288	14	Direction 2190775-100	0
i thru iv	16	Direction 2173224-100	6	Direction 2173228-100	11
Direction 2173221-100	5	Direction 2173225-100	5	Direction 2237257-100	4
Direction 2173222-100	5	Direction 2196272-100	1	Direction 2173229-100	5
Direction 2173223-100	4	Direction 2173227-100	5		

THIS PAGE INTENTIONALLY LEFT BLANK.